



car-pdi-check



Comprehensive Car Inspection Report



Thorough inspection with
300+ quality checks



Precise insights from
experienced technicians



Trusted by
Over 5000+ customers



5276+

Inspection
Completed

25+

Cities
Available

4.7+

Average
Rating



Vehicle Details

Vehicle Name : XUV 3XO

Vehicle Manufacturer : MAHINDRA

PDI Location : LATUR

Date of PDI : 20/07/2026

Vehicle MFG Date : 2026 JULY

Tyre Batch : MATCHED

VIN Number : MA1NS2EW1T2G60422

KM Driven : 08.8 KM

Name of the Evaluator : PRAFUL .M

**OVERALL RATING
OF THE INSPECTED
VEHICLE**

5 / 5

RECOMMENDATIONS :

Inspection Summary

This section provides a comprehensive evaluation of the most recent car assessment, meticulously divided into five key categories to offer an in-depth and accurate overview

Exterior

We have inspected your vehicle's exterior and found that it is in overall good condition, no major damages or structural issues were observed during the inspection.

5 / 5

Engine & Transmission

The engine and transmission systems were checked and found to be in perfect working condition.

5 / 5

Steering, Suspension & Brakes

Your car's steering, suspension, and brakes are all in good condition. There are no issues that were founded.

5 / 5

Air Conditioning

The air conditioning in your car is working perfectly. The AC, heater, and climate control are all functional.

5 / 5

Electricals & Features

Your car has all the electrical features working well, including power windows, airbags, music system, and a reverse camera.

5 / 5

Interiors

Vehicle's interior is in perfect and no issues or irregularity founded during the inspection.

5 / 5

Tyres

All the four tyres and one stepny tyre is in perfect condition and no irregularity founded during the inspection.

5 / 5

Exterior Panels

The bonnet, doors, rear door, fenders, and running board are all in factory-standard condition. No issues or irregularities were observed during inspection.

5 / 5



ISSUES FOUNDED



**DPF FILTER WARNING IS COMING BUT DPF
IS FULL.**



CLEANING IS REQUIRED.



OIL LEVEL IS LOW.



Vehicle Images

EXTERIOR / BODY & STRUCTURE :











PANEL GAPS :





INTSTRUMENT CLUSTER :



RO & VALID TAGS:



NGTG1788XJ

A3STLTHBLK



MA1NS2EW1T2G60422

Mfg Sr No:

Z650544

Model Code:

AS22JPEW5T103E00XJ

Model Desc:

XUV3XO AX5 DS MT



India
15G1736
EWTZG26027



M&M NO: 0120AS200121N
ZRAI NO: 021 0006 00
MEETS: IS 15140:2018
AIS037 TAC NO: A40301
DATE OF MFG: 08/07/2025

Mahindra

AIRBAG

07 45773





V - Issued Under Rule 55 of CGST/SGST Rules, 2017

Mahindra & Mahindra, AS, P-1 J.D.C. Sat Nashik-422007 Maharashtra GSTIN No:27AAACM3025E1ZZ	Automotive Sector Plot 126, MIDC, Satpur Nashik-422007 N GSTN No:27AAACM3025E1ZZ Place of Supp
--	--

challan No.: 9223398378 ODN NO.: DO01272700279088 Date & Time : 15.07.2026 20:03:11


	Colour	Part No.	Description of Vehicle		
26027	A3STLTHBLK	AS22JPEWST103E00XJ	XUV3XO AX5 DS MT XJ		
UOM	QTY	CGST %	& Amount	SGST %	& Amount
EA	1.000	9.00 %	76915.00	9.00 %	76915.00

H EIGHT THOUSAND FOUR HUNDRED FORTY FIVE Rupees NINETY

0422

789

Panish K+MC



For MAHINDRA

Digitally Signed by:
DS MAHINDRA ANT
15/07/2026@20:03:18
Approved by Vijaykum

Authi



Mahindra
—:1401CAA04530N:DD013K
W/H BATTERY NEGATIVE CABLE
ECD : 20/01/2020, S201-EN-A003
DATE: 03/07/26 TIME: 08:37:20



RECOMMENDED FLUIDS

FLUIDS FOR	RECOMMENDED BRAND
ENGINE	MAXIMILE ULTRA
TRANSAXLE	MAXIMILE <i>SYNTEC F2</i>
COOLING SYSTEM	MAXIMILE ULTRACOOOL
BRAKE FLUID	MAXIMILE DOT 4



TYRES :



TYRE BATCH :



TYRE TEAD THICKNESS GUAGE :



TYRE TEADS :





LIGHTS / OTHER FEATURES :









Rear Taillights Working,
Rear Indicator Working
Rear Reverse Light Working




Headlight High Beam and Low
Beam Working
Front Side FOG Lamp
Working Properly



ENGINE & TRANSMISSION :











TOOL KIT / STEPNY :



INTERIOR:







DOORS EXTERIOR :



DOORS INTERIOR :






DOORS HOLDINGS/GAPS :





CHARGER NOZEL :



CHARGER / TOOLKIT :



PANEL HOLDINGS :



>>> VIN NUMBER :



>>> INFOTAINMENT / CAMERA SYSTEM :





UNDER BODY :





BATTERY :



BOOTSPACE :





POWER CONTROLS :







SUSPENSIONS / BRAKES :





EXTERIOR PANELS :



SUNROOF / MOONROOF :



OVRMS :



STEERING WHEEL :



ACCELERATOR, CLUTCH AND BREAK :



KEYS :



TEMPERATURE METER READINGS :



FUEL NOZEL :



AIRBAG TAGS :






CAMERAS :



PTG READINGS :





OTHERS :



OBD READING :



CNG CYLINDERS :





Thank you for choosing us!



We truly appreciate your decision to prioritize the safety and maintenance of your vehicle. By opting for a thorough inspection, you're ensuring not only the longevity of your car but also peace of mind for you and your loved ones.

Should you have any questions about the inspection report or need further assistance, please don't hesitate to reach out. We're here to help and ensure your vehicle remains in top condition.

Thank you once again for your trust and patronage.



CAR PDI CHECK

www.car-pdi-check.com



THIS REPORT CANNOT BE USED FOR LEGAL PURPOSES



9421762760



CAR_PDI_CHECK



car-pdi-check.com

